



MASH TEST 4-12 ON T2P RETROFIT BRIDGE RAIL



Crash testing performed at:
TTI Proving Ground
1254 Avenue A, Building 7091
Bryan, TX 77807

Test Report 0-7086-R5

Cooperative Research Program

**TEXAS A&M TRANSPORTATION INSTITUTE
COLLEGE STATION, TEXAS**

TEXAS DEPARTMENT OF TRANSPORTATION

in cooperation with the
Federal Highway Administration and the
Texas Department of Transportation
<http://tti.tamu.edu/documents/0-7086-R5.pdf>

| | | | | | |
|--|--|--|--|--|-----------|
| 1. Report No. FHWA/TX-22/0-7086-R5 | | 2. Government Accession No. | | 3. Recipient's Catalog No. | |
| 4. Title and Subtitle MASH TEST 4-12 ON T2P RETROFIT BRIDGE RAIL | | | | 5. Report Date Published: September 2021 | |
| | | | | 6. Performing Organization Code | |
| 7. Author(s) William F. Williams, Wanda L. Menges, William J. L. Schroeder, Bill L. Griffith, Sarah A. Wegenast, and Darrell L. Kuhn | | | | 8. Performing Organization Report No. Report 0-7086-R5 | |
| 9. Performing Organization Name and Address Texas A&M Transportation Institute The Texas A&M University System College Station, Texas 77843-3135 | | | | 10. Work Unit No. (TRAIS) | |
| | | | | 11. Contract or Grant No. Project 0-7086 | |
| 12. Sponsoring Agency Name and Address Texas Department of Transportation Research and Technology Implementation Office 125 E. 11 th Street Austin, Texas 78701-2483 | | | | 13. Type of Report and Period Covered Technical Report: September 2020–August 2021 | |
| | | | | 14. Sponsoring Agency Code | |
| 15. Supplementary Notes Project performed in cooperation with the Texas Department of Transportation and the Federal Highway Administration. Project Title: Roadside Safety Device Analysis, Testing, and Evaluation Program URL: http://tti.tamu.edu/documents/0-7086-R5.pdf | | | | | |
| 16. Abstract <p>The purpose of the test reported herein was to assess the performance of a retrofit rail for the Texas Department of Transportation (TxDOT) T2P bridge rail according to the safety-performance evaluation guidelines included in the American Association of State Highway and Transportation Officials (AASHTO) <i>Manual for Assessing Safety Hardware (MASH)</i>. The crash test was performed in accordance with <i>MASH</i> Test 4-12, which involves a 10000S vehicle weighing 22,000 lb impacting the retrofit bridge rail while traveling at a nominal impact speed and angle of 56 mi/h and 15 degrees.</p> <p>This report provides details on the TxDOT T2P retrofit bridge rail, the crash test and results, and the performance assessment of the TxDOT T2P retrofit bridge rail for <i>MASH</i> Test 4-12 longitudinal barrier evaluation criteria.</p> <p>The TxDOT T2P retrofit bridge rail met the performance criteria for <i>MASH</i> Test 4-12 for longitudinal barriers.</p> | | | | | |
| 17. Key Words Longitudinal Barriers, Bridge Rail, Retrofit Rail, Tubular Rail Elements, <i>MASH</i> , Crash Testing, Roadside Safety | | | 18. Distribution Statement No restrictions. This document is available to the public through NTIS: National Technical Information Service Alexandria, Virginia http://www.ntis.gov | | |
| 19. Security Classif. (of this report) Unclassified | | 20. Security Classif. (of this page) Unclassified | | 21. No. of Pages 78 | 22. Price |

MASH TEST 4-12 ON T2P RETROFIT BRIDGE RAIL

by

William F. Williams, P.E.
Associate Research Engineer
Texas A&M Transportation Institute

Wanda L. Menges
Research Specialist
Texas A&M Transportation Institute

William J. L. Schroeder
Engineering Research Associate
Texas A&M Transportation Institute

Bill L. Griffith
Research Specialist
Texas A&M Transportation Institute

Sarah A. Wegenast
Research Associate
Texas A&M Transportation Institute

and

Darrell L. Kuhn, P.E.
Research Specialist
Texas A&M Transportation Institute

Report 0-7086-R5

Project 0-7086

Project Title: Roadside Safety Device Analysis, Testing, and Evaluation Program

Performed in cooperation with the
Texas Department of Transportation
and the
Federal Highway Administration

Published: September 2021

TEXAS A&M TRANSPORTATION INSTITUTE
College Station, Texas 77843-3135

DISCLAIMER

This research was performed in cooperation with the Texas Department of Transportation (TxDOT) and the Federal Highway Administration (FHWA). The contents of this report reflect the views of the authors, who are responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official view or policies of FHWA or TxDOT. This report does not constitute a standard, specification, or regulation.

This report is not intended for construction, bidding, or permit purposes. The engineer (researcher) in charge of the project was William F. Williams, P.E., #71898.

The United States Government and the State of Texas do not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the object of this report.

TTI PROVING GROUND DISCLAIMER

The results of the crash testing reported herein apply only to the article tested.

REPORT AUTHORIZATION

| | |
|---|---|
| <p>DocuSigned by: <i>Bill Griffith</i> 44A122CB271845B...</p> <hr/> <p>Bill L. Griffith, Research Specialist Deputy Quality Manager</p> | <p>DocuSigned by: <i>Darrell L. Kuhn</i> D4CC23E83D384E7...</p> <hr/> <p>Darrell L. Kuhn, P.E., Research Specialist Quality Manager</p> |
| <p>DocuSigned by: <i>Matt Robinson</i> EAA22BFA5BFD417...</p> <hr/> <p>Matthew N. Robinson, Research Specialist Test Facility Manager & Technical Manager</p> | <p>DocuSigned by: <i>William F. Williams</i> 2B8AC4D2D3784AE...</p> <hr/> <p>William F. Williams, P.E. Associate Research Engineer</p> |

ACKNOWLEDGMENTS

This project was conducted in cooperation with TxDOT and FHWA. The authors would like to thank Taya Retterer, bridge standards engineer with the TxDOT Bridge Division, for her assistance on this project. Taya's input and guidance made this truly a great research project.

TABLE OF CONTENTS

| | Page |
|--|-----------|
| List of Figures | x |
| List of Tables | xi |
| Chapter 1. Introduction | 1 |
| 1.1. Background..... | 1 |
| 1.2. Objective..... | 1 |
| Chapter 2. System Details | 3 |
| 2.1. Test Article and Installation Details | 3 |
| 2.2. Design Modifications during Test | 3 |
| 2.3. Material Specifications | 3 |
| Chapter 3. Test Requirements and Evaluation Criteria | 7 |
| 3.1. Crash Test Performed/Matrix | 7 |
| 3.2. Evaluation Criteria..... | 7 |
| Chapter 4. Test Conditions | 9 |
| 4.1. Test Facility | 9 |
| 4.2. Vehicle Tow and Guidance System..... | 9 |
| 4.3. Data Acquisition System | 9 |
| 4.3.1. Vehicle Instrumentation and Data Processing | 9 |
| 4.3.2. Anthropomorphic Dummy Instrumentation | 10 |
| 4.3.3. Photographic Instrumentation Data Processing | 10 |
| Chapter 5. MASH Test 4-12 (Crash Test No. 440861-2) | 13 |
| 5.1. Test Designation and Actual Impact Conditions | 13 |
| 5.2. Weather Conditions | 13 |
| 5.3. Test Vehicle..... | 13 |
| 5.4. Test Description..... | 14 |
| 5.5. Damage to Test Installation..... | 14 |
| 5.6. Damage to Test Vehicle | 15 |
| 5.7. Vehicle Instrumentation | 15 |
| Chapter 6. Summary and Conclusions | 21 |
| 6.1. Assessment of Test Results | 21 |
| 6.2. Conclusions | 21 |
| Chapter 7. Implementation | 23 |
| References | 25 |
| Appendix A. Details of TxDOT T2P Retrofit Bridge Rail | 27 |
| Appendix B. Supporting Certification Documents | 35 |
| Appendix C. MASH Test 4-12 (Crash Test No. 440861-2) | 55 |
| C.1. Vehicle Properties and Information..... | 55 |
| C.2. Sequential Photographs | 57 |
| C.3. Vehicle Angular Displacements | 58 |
| C.4. Vehicle Accelerations | 58 |

LIST OF FIGURES

| | Page |
|--|-------------|
| Figure 2.1. TxDOT T2P Retrofit Bridge Rail Details..... | 4 |
| Figure 2.2. TxDOT T2P Retrofit Bridge Rail prior to Testing. | 5 |
| Figure 3.1. Target CIP for <i>MASH</i> Test 4-12 on TxDOT T2P Retrofit Bridge Rail..... | 7 |
| Figure 5.1. TxDOT T2P Retrofit Bridge Rail/Test Vehicle Geometrics for Test No. 440861-2. | 13 |
| Figure 5.2. Test Vehicle before Test No. 440861-2..... | 14 |
| Figure 5.3. TxDOT T2P Retrofit Bridge Rail after Test No. 440861-2..... | 17 |
| Figure 5.4. Field Side of TxDOT T2P Retrofit Bridge Rail after Test No. 440861-2. | 18 |
| Figure 5.5. Test Vehicle after Test No. 440861-2..... | 19 |
| Figure 5.6. Interior of Test Vehicle after Test No. 440861-2. | 19 |
| Figure 5.7. Summary of Results for <i>MASH</i> Test 4-12 on TxDOT T2P Retrofit Bridge Rail..... | 20 |

LIST OF TABLES

| | Page |
|---|-------------|
| Table 2.1. Concrete Strengths..... | 3 |
| Table 3.1. Test Conditions and Evaluation Criteria Specified for <i>MASH</i> TL-4 Longitudinal Barriers..... | 7 |
| Table 3.2. Evaluation Criteria Required for <i>MASH</i> TL-4 Longitudinal Barriers..... | 8 |
| Table 5.1. Events during Test No. 440861-2..... | 14 |
| Table 5.2. Post Lean after Test No. 440861-2..... | 16 |
| Table 6.1. Performance Evaluation Summary for <i>MASH</i> Test 4-12 on TxDOT T2P Retrofit Bridge Rail..... | 22 |

SI* (MODERN METRIC) CONVERSION FACTORS

APPROXIMATE CONVERSIONS TO SI UNITS

| Symbol | When You Know | Multiply By | To Find | Symbol |
|---|----------------------------|----------------------------|----------------------------|-----------------|
| LENGTH | | | | |
| in | inches | 25.4 | millimeters | mm |
| ft | feet | 0.305 | meters | m |
| yd | yards | 0.914 | meters | m |
| mi | miles | 1.61 | kilometers | km |
| AREA | | | | |
| in ² | square inches | 645.2 | square millimeters | mm ² |
| ft ² | square feet | 0.093 | square meters | m ² |
| yd ² | square yards | 0.836 | square meters | m ² |
| ac | acres | 0.405 | hectares | ha |
| mi ² | square miles | 2.59 | square kilometers | km ² |
| VOLUME | | | | |
| fl oz | fluid ounces | 29.57 | milliliters | mL |
| gal | gallons | 3.785 | liters | L |
| ft ³ | cubic feet | 0.028 | cubic meters | m ³ |
| yd ³ | cubic yards | 0.765 | cubic meters | m ³ |
| NOTE: volumes greater than 1000L shall be shown in m ³ | | | | |
| MASS | | | | |
| oz | ounces | 28.35 | grams | g |
| lb | pounds | 0.454 | kilograms | kg |
| T | short tons (2000 lb) | 0.907 | megagrams (or metric ton") | Mg (or "t") |
| TEMPERATURE (exact degrees) | | | | |
| °F | Fahrenheit | 5(F-32)/9 or (F-32)/1.8 | Celsius | °C |
| FORCE and PRESSURE or STRESS | | | | |
| lbf | poundforce | 4.45 | newtons | N |
| lbf/in ² | poundforce per square inch | 6.89 | kilopascals | kPa |

APPROXIMATE CONVERSIONS FROM SI UNITS

| Symbol | When You Know | Multiply By | To Find | Symbol |
|-------------------------------------|-----------------------------|-------------|----------------------------|--------------------|
| LENGTH | | | | |
| mm | millimeters | 0.039 | inches | in |
| m | meters | 3.28 | feet | ft |
| m | meters | 1.09 | yards | yd |
| km | kilometers | 0.621 | miles | mi |
| AREA | | | | |
| mm ² | square millimeters | 0.0016 | square inches | in ² |
| m ² | square meters | 10.764 | square feet | ft ² |
| m ² | square meters | 1.195 | square yards | yd ² |
| ha | hectares | 2.47 | acres | ac |
| km ² | Square kilometers | 0.386 | square miles | mi ² |
| VOLUME | | | | |
| mL | milliliters | 0.034 | fluid ounces | oz |
| L | liters | 0.264 | gallons | gal |
| m ³ | cubic meters | 35.314 | cubic feet | ft ³ |
| m ³ | cubic meters | 1.307 | cubic yards | yd ³ |
| MASS | | | | |
| g | grams | 0.035 | ounces | oz |
| kg | kilograms | 2.202 | pounds | lb |
| Mg (or "t") | megagrams (or "metric ton") | 1.103 | short tons (2000lb) | T |
| TEMPERATURE (exact degrees) | | | | |
| °C | Celsius | 1.8C+32 | Fahrenheit | °F |
| FORCE and PRESSURE or STRESS | | | | |
| N | newtons | 0.225 | poundforce | lbf |
| kPa | kilopascals | 0.145 | poundforce per square inch | lb/in ² |

*SI is the symbol for the International System of Units

Chapter 1. INTRODUCTION

1.1. BACKGROUND

Roadway departure crashes are the most common type of crash in Texas. These crashes represent over 45 percent of all fatal crashes and 34 percent of all serious injury crashes. Texas data show that there were 9,560 fatal and 30,766 serious injury roadway departure crashes from 2010–2016. Roadside safety devices shield motorists from roadside hazards such as non-traversable terrain and fixed objects, thereby reducing injuries and fatalities associated with roadway departure crashes. To improve the safety of the motoring public, there is a need to develop new or improved safety devices that accommodate a variety of site conditions and placement locations, as well as a changing vehicle fleet. To this end, researchers at the Texas A&M Transportation Institute (TTI) have sought to provide the Texas Department of Transportation (TxDOT) with a mechanism to quickly and effectively address high-priority issues related to roadside safety devices. TTI researchers provide results on new and improved safety features that minimize the consequences of vehicles leaving the road and reduce injuries and fatalities associated with roadway departure crashes. The researchers have developed roadside safety devices to meet the 2016 edition of the American Association of State Highway and Transportation Officials (AASHTO) *Manual for Assessing Safety Hardware (MASH)* roadside safety criteria to address the continuing trend of larger vehicles in the statewide vehicle fleet (1).

1.2. OBJECTIVE

The purpose of the test reported herein was to assess the performance of a retrofit rail for TxDOT's T2P bridge rail according to the safety-performance evaluation guidelines included in *MASH*. The crash test was performed in accordance with *MASH* Test 4-12, which involves a 10000S vehicle weighing 22,000 lb impacting the retrofit bridge rail while traveling at a nominal impact speed and angle of 56 mi/h and 15 degrees.

This report provides details on the TxDOT T2P retrofit bridge rail, the crash test and results, and the performance assessment of the TxDOT T2P retrofit bridge rail for *MASH* Test 4-12 longitudinal barrier evaluation criteria.

Chapter 2. SYSTEM DETAILS

2.1. TEST ARTICLE AND INSTALLATION DETAILS

The test installation was 124 ft long and consisted of three steel rails attached to steel posts, which were mounted on a cantilevered reinforced concrete deck and curb. The deck was 6 inches thick, and the curb was 9 inches tall. The top rail was a hollow structural section (HSS) 4½-inch-diameter section, and the two lower rails were HSS rectangular sections, 2 inches tall and 6 inches wide. Internal rail sleeves measuring 28 inches long were centered at each rail splice. The distance from the top of the deck to the top of each rail was 18 inches, 28 inches, and 42 inches.

The posts were fabricated from ¾-inch-thick plates. They were spaced at 96-inch centers, and each was secured to the deck by four 7/8-inch-diameter bolts that were cast in the concrete.

Figure 2.1 presents the overall information on the TxDOT T2P retrofit bridge rail, and Figure 2.2 provides photographs of the installation. Appendix A provides further details on the TxDOT T2P retrofit bridge rail. Drawings were provided by the TTI Proving Ground, and construction was performed Tucker Construction and supervised by TTI Proving Ground personnel.

2.2. DESIGN MODIFICATIONS DURING TEST

No modifications were made to the installation during the testing phase.


2.3. MATERIAL SPECIFICATIONS

The specified compressive strength of the concrete used in the deck and curb was 4000 psi. Table 2.1 shows the average compressive strengths of the concrete on the date of the test, July 23, 2021.

Table 2.1. Concrete Strengths.

| Location | Design Strength (psi) | Average Strength (psi) | Age (days) | Detailed Location |
|---------------|-----------------------|------------------------|------------|-----------------------------|
| Wall and Deck | 3600 | 4713 | 97 | South Half of Wall and Deck |
| Wall and Deck | 3600 | 5113 | 97 | North Half of Wall and Deck |
| Curb | 4000 | 4487 | 38 | 100% of curb |

Appendix B provides material certification documents for the materials used to install/construct the TxDOT T2P retrofit bridge rail.



- 1a. All Posts, Hardware and Rail components shall be galvanized.
- 1b. Typical 3 places at each Post. Plate Washer, Hex Nut, and Lock Washer typical x 2 at each U-bolt location.

| | |
|--------------|---|
| | Roadside Safety and Physical Security Division - Proving Ground |
| | Project #440861-2 T2P Retrofit |
| Drawn by GES | Scale 1:200 |
| Sheet 1 of 8 | Test Installation |

Q:\Accreditation-17025-2017\EIR-000 Project Files\440861 - TxDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting, 440861-2\440861-2 Drawing

Figure 2.1. TxDOT T2P Retrofit Bridge Rail Details.



Figure 2.2. TxDOT T2P Retrofit Bridge Rail prior to Testing.

Chapter 3. TEST REQUIREMENTS AND EVALUATION CRITERIA

3.1. CRASH TEST PERFORMED/MATRIX

Table 3.1 shows the test conditions and evaluation criteria for *MASH* TL-4 for longitudinal barriers. *MASH* Tests 4-10 and 4-11 were not performed for this project since these tests were performed previously on the TxDOT T2P bridge rail. The researchers felt that only *MASH* Test 4-12 (strength test) was necessary for this retrofit bridge rail design.

Table 3.1. Test Conditions and Evaluation Criteria Specified for *MASH* TL-4 Longitudinal Barriers.

| Test Article | Test Designation | Test Vehicle | Impact Conditions | | Evaluation Criteria |
|----------------------|------------------|--------------|-------------------|-------|---------------------|
| | | | Speed | Angle | |
| Longitudinal Barrier | 4-10 | 1100C | 62 mi/h | 25° | A, D, F, H, I |
| | 4-11 | 2270P | 62 mi/h | 25° | A, D, F, H, I |
| | 4-12 | 10000S | 56 mi/h | 15° | A, D, G |

The target critical impact point (CIP) for *MASH* Test 4-12 was determined using the information provided in *MASH* Section 2.2.1 and Section 2.3.2. Figure 3.1 shows the target CIP for *MASH* Test 4-12 on the TxDOT T2P retrofit bridge rail.




Figure 3.1. Target CIP for *MASH* Test 4-12 on TxDOT T2P Retrofit Bridge Rail.

The crash test and data analysis procedures were in accordance with guidelines presented in *MASH*. Chapter 4 presents brief descriptions of these procedures.

3.2. EVALUATION CRITERIA

The appropriate safety evaluation criteria from Tables 2-2 and 5-1 of *MASH* were used to evaluate the crash test reported herein. Table 3.1 lists the test conditions and evaluation criteria required for *MASH* Test 4-12, and Table 3.2 provides detailed information on the evaluation criteria. An evaluation of the crash test results is presented in Chapter 6.

Table 3.2. Evaluation Criteria Required for MASH TL-4 Longitudinal Barriers.

| Evaluation Factors | Evaluation Criteria | MASH Test |
|----------------------------|---|----------------------|
| Structural Adequacy | A. <i>Test article should contain and redirect the vehicle or bring the vehicle to a controlled stop; the vehicle should not penetrate, underide, or override the installation although controlled lateral deflection of the test article is acceptable.</i> | 4-10, 4-11, and 4-12 |
| Occupant Risk | D. <i>Detached elements, fragments, or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present undue hazard to other traffic, pedestrians, or personnel in a work zone. Deformations of, or intrusions into, the occupant compartment should not exceed limits set forth in Section 5.2.2 and Appendix E of MASH.</i> | 4-10, 4-11, and 4-12 |
| | F. <i>The vehicle should remain upright during and after collision. The maximum roll and pitch angles are not to exceed 75 degrees.</i> | 4-10 and 4-11 |
| | G. <i>It is preferable, although not essential, that the vehicle remain upright during and after the collision.</i> | 4-12 |
| | H. <i>Occupant impact velocities (OIV) should satisfy the following limits: Preferred value of 30 ft/s, or maximum allowable value of 40 ft/s.</i> | 4-10 and 4-11 |
| | I. <i>The occupant ridedown accelerations should satisfy the following: Preferred value of 15.0 g, or maximum allowable value of 20.49 g.</i> | 4-10 and 4-11 |

Chapter 4. TEST CONDITIONS

4.1. TEST FACILITY

The full-scale crash test reported herein was performed at the TTI Proving Ground, an International Standards Organization (ISO)/International Electrotechnical Commission (IEC) 17025-accredited laboratory with American Association for Laboratory Accreditation (A2LA) Mechanical Testing Certificate 2821.01. The full-scale crash test was performed according to TTI Proving Ground quality procedures, as well as *MASH* guidelines and standards.

The test facilities of the TTI Proving Ground are located on The Texas A&M University System RELIS Campus, which consists of a 2000-acre complex of research and training facilities situated 10 mi northwest of the flagship campus of Texas A&M University. The site, formerly a United States Army Air Corps base, has large expanses of concrete runways and parking aprons well suited for experimental research and testing in the areas of vehicle performance and handling, vehicle-roadway interaction, highway pavement durability and efficacy, and roadside safety hardware and perimeter protective device evaluation. The site selected for construction and testing of the TxDOT T2P retrofit bridge rail was along the edge of an out-of-service apron. The apron consists of an unreinforced jointed-concrete pavement in 12.5-ft × 15-ft blocks nominally 6 inches deep. The aprons were built in 1942, and the joints have some displacement but are otherwise flat and level.

4.2. VEHICLE TOW AND GUIDANCE SYSTEM

The vehicle was towed into the test installation using a steel cable guidance and reverse tow system. A steel cable for guiding the test vehicle was tensioned along the path, anchored at each end, and threaded through an attachment to the front wheel of the test vehicle. An additional steel cable was connected to the test vehicle, passed around a pulley near the impact point and through a pulley on the tow vehicle, and then anchored to the ground such that the tow vehicle moved away from the test site. A 2:1 speed ratio between the test and tow vehicle existed with this system. Just prior to impact with the installation, the test vehicle was released and ran unrestrained. The vehicle remained freewheeling (i.e., no steering or braking inputs) until it cleared the immediate area of the test site.

4.3. DATA ACQUISITION SYSTEM

4.3.1. Vehicle Instrumentation and Data Processing

The test vehicle was instrumented with a self-contained onboard data acquisition system. The signal conditioning and acquisition system is a multichannel data acquisition system (DAS) produced by Diversified Technical Systems Inc. The accelerometers, which measure the x, y, and z axis of vehicle acceleration, are strain gauge type with linear millivolt output proportional to acceleration. Angular rate sensors, measuring vehicle roll, pitch, and yaw rates, are ultra-small, solid-state units designed for crash test service. The data acquisition hardware and software conform to the latest SAE J211, Instrumentation for Impact Test. Each channel is capable of providing precision amplification, scaling, and filtering based on transducer specifications and calibrations. During the test, data are recorded from each channel at a rate of

10,000 samples per second with a resolution of one part in 65,536. Once data are recorded, internal batteries back up the data inside the unit in case the primary battery cable is severed. Initial contact of a pressure tape switch on the vehicle bumper provides a time zero mark and initiates the recording process. After each test, the data are downloaded from the DAS unit into a laptop computer at the test site. The Test Risk Assessment Program (TRAP) software then processes the raw data to produce detailed reports of the test results.

Each DAS is returned to the factory annually for complete recalibration and to ensure that all instrumentation used in the vehicle conforms to the specifications outlined by SAE J211. All accelerometers are calibrated annually by means of an ENDEVCO® 2901 precision primary vibration standard. This standard and its support instruments are checked annually and receive a National Institute of Standards Technology (NIST) traceable calibration. The rate transducers used in the DAS receive calibration via a Genisco Rate-of-Turn table. The subsystems of each data channel are also evaluated annually, using instruments with current NIST traceability, and the results are factored into the accuracy of the total data channel per SAE J211. Calibrations and evaluations are also made anytime data are suspect. Acceleration data are measured with an expanded uncertainty of ± 1.7 percent at a confidence factor of 95 percent ($k = 2$).

TRAP uses the DAS-captured data to compute the occupant/compartment impact velocities, time of occupant/compartment impact after vehicle impact, and highest 10-millisecond (ms) average ridedown acceleration. TRAP calculates change in vehicle velocity at the end of a given impulse period. In addition, maximum average accelerations over 50-ms intervals in each of the three directions are computed. For reporting purposes, the data from the vehicle-mounted accelerometers are filtered with an SAE Class 180-Hz low-pass digital filter, and acceleration versus time curves for the longitudinal, lateral, and vertical directions are plotted using TRAP.

TRAP uses the data from the roll, pitch, and yaw rate transducers to compute angular displacement in degrees at 0.0001-s intervals, and then plots yaw, pitch, and roll versus time. These displacements are in reference to the vehicle-fixed coordinate system with the initial position and orientation being initial impact. Rate-of-rotation data are measured with an expanded uncertainty of ± 0.7 percent at a confidence factor of 95 percent ($k = 2$).

4.3.2. Anthropomorphic Dummy Instrumentation

MASH does not recommend or require use of a dummy in the 10000S vehicle, and no dummy was placed in the vehicle.

4.3.3. Photographic Instrumentation Data Processing

Photographic coverage of the test included three digital high-speed cameras:

- One placed overhead with a field of view perpendicular to the ground and directly over the impact point.
- One placed upstream from the installation at an angle to have a field of view of the interaction of the rear of the vehicle with the installation.
- A third placed with a field of view parallel to and aligned with the installation at the downstream end.

A flashbulb on the impacting vehicle was activated by a pressure-sensitive tape switch to indicate the instant of contact with the TxDOT T2P retrofit bridge rail. The flashbulb was visible from each camera. The video files from these digital high-speed cameras were analyzed to observe phenomena occurring during the collision and to obtain time-event, displacement, and angular data. A digital camera recorded and documented conditions of the test vehicle and the installation before and after the test.

Chapter 5. MASH TEST 4-12 (CRASH TEST NO. 440861-2)

5.1. TEST DESIGNATION AND ACTUAL IMPACT CONDITIONS

MASH Test 4-12 involves a 10000S vehicle weighing 22,000 lb \pm 660 lb impacting the CIP of the longitudinal barrier at an impact speed of 56 mi/h \pm 2.5 mi/h and an angle of 15 degrees \pm 1.5 degrees. The CIP for MASH Test 4-12 on the TxDOT T2P retrofit bridge rail was 5 ft \pm 1 ft upstream of the centerline of post 6. Figure 3.1 and Figure 5.1 depict the target impact setup.



Figure 5.1. TxDOT T2P Retrofit Bridge Rail/Test Vehicle Geometrics for Test No. 440861-2.

The 10000S vehicle weighed 22,540 lb, and the actual impact speed and angle were 56.3 mi/h and 14.2 degrees. The actual impact point was 4.4 ft upstream of the centerline of post 6. Minimum target impact severity (IS) was 142 kip-ft, and actual IS was 144 kip-ft.

5.2. WEATHER CONDITIONS

The test was performed on the morning of July 23, 2021. Weather conditions at the time of testing were as follows: wind speed: 8 mi/h; wind direction: 209 degrees (vehicle was traveling at a heading of 335 degrees); temperature: 86°F; relative humidity: 71 percent.

5.3. TEST VEHICLE

Figure 5.2 shows the 2012 Hino 338 single-unit truck (SUT) used for the crash test. The vehicle's test inertia weight was 22,540 lb, and its gross static weight was 22,540 lb. The height to the lower edge of the vehicle bumper was 18.75 inches, and the height to the upper edge of the bumper was 31.50 inches. The height to the center of gravity of the vehicle's ballast was 63.75 inches. Table C.1 in Appendix C.1 gives additional dimensions and information on the vehicle. The vehicle was directed into the installation using a cable reverse tow and guidance system, and was released to be freewheeling and unrestrained just prior to impact.



Figure 5.2. Test Vehicle before Test No. 440861-2.

5.4. TEST DESCRIPTION

Table 5.1 lists events that occurred during Test No. 440861-2. Figures C.1 and C.2 in Appendix C.2 present sequential photographs during the test.

Table 5.1. Events during Test No. 440861-2.

| Time (s) | Events |
|-----------------|--|
| 0.000 | Vehicle impacts retrofit bridge rail |
| 0.035 | Vehicle's front driver-side tire lifts off the pavement |
| 0.050 | Vehicle begins to redirect |
| 0.141 | Vehicle's right front tire lifts off the pavement |
| 0.245 | Vehicle's right rear tire lifts off the pavement |
| 0.264 | Vehicle travels parallel with the retrofit bridge rail |
| 0.248 | Vehicle's rear bumper contacts the retrofit bridge rail |
| 0.381 | Vehicle's left front tire makes contact with the pavement |
| 1.328 | Vehicle's right front tire makes contact with the pavement |

For longitudinal barriers, it is desirable for the vehicle to redirect and exit the barrier within the exit box criteria (not less than 65.6 ft for heavy vehicles). The test vehicle exited within the exit box criteria defined in *MASH*. Brakes on the vehicle were applied at 2.7 s after impact, and the vehicle subsequently came to rest 241 ft downstream of the point of impact and 12 ft toward the field side of the bridge rail.

5.5. DAMAGE TO TEST INSTALLATION

Figure 5.3 and Figure 5.4 show the damage to the TxDOT T2P retrofit bridge rail, and Table 5.2 shows post lean after the test. There was major cracking of the deck on the traffic side of the curb up to the edge of the field joint, which extended from post 3 to 2 ft downstream from post 10. There was also cracking under the deck from the field joint to 1 ft downstream from post 7, which ran along the anchor bolts, and from the field joint to post 7, there was a crack where the deck and wall intersected. The curb had some spalling and exposed rebar on the traffic and field side at post 6, and the curb downstream of the field joint was 3 inches lower on the field side and 1¼ inches lower on the traffic side than the curb upstream of the joint. The lower

rail was deformed just downstream of impact and was 6 inches lower than its pre-impact height. The existing cracks in the curb were outlined in black, and the cracks that occurred post-impact were outlined in red. Working width* was 64.4 inches, and height of working width was 144.3 inches. Maximum dynamic deflection during the test was 14.9 inches, and maximum permanent deformation was 9.0 inches.

5.6. DAMAGE TO TEST VEHICLE



Figure 5.5 shows the damage sustained by the vehicle. The front bumper, hood, left front tire and rim, left front U-bolts, left rear outer tire and rim, and left rear corner of the cargo box were damaged. No damage to the fuel tank was observed. Maximum exterior crush to the vehicle was 10.0 inches in the front plane at the left front corner at bumper height. No occupant compartment deformation or intrusion was noted. Figure 5.6 shows the interior of the vehicle.

5.7. VEHICLE INSTRUMENTATION

Data from the accelerometers were digitized for informational purposes only and are reported in Figure 5.7. Figure C.3 in Appendix C.3 shows the vehicle angular displacements, and

* Per *MASH*, “The working width is the maximum dynamic lateral position of any major part of the system or vehicle. These measurements are all relative to the pre-impact traffic face of the test article.” In other words, working width is the total barrier width plus the maximum dynamic intrusion of any portion of the barrier or test vehicle past the field side edge of the barrier.

Figures C.4 through C.9 in Appendix C.4 show acceleration versus time traces. Figure 5.7 summarizes pertinent information from the test.

Table 5.2. Post Lean after Test No. 440861-2.

| Post No. | Lean from Vertical |
|-----------------|---------------------------|
| 5 | 6° |
| 6 | 11.5° |
| 7 | 11° |
| 8 | 4.5° |



Figure 5.3. TxDOT T2P Retrofit Bridge Rail after Test No. 440861-2.




Figure 5.4. Field Side of TxDOT T2P Retrofit Bridge Rail after Test No. 440861-2.



Figure 5.5. Test Vehicle after Test No. 440861-2.



Figure 5.6. Interior of Test Vehicle after Test No. 440861-2.



| | | |
|---------------------------------------|---|--|
| General Information | | Texas A&M Transportation Institute (TTI) |
| Test Agency | MASH Test 4-12 | |
| Test Standard | 440861-2 | |
| TTI Test No. | 2021-07-23 | |
| Test Date | | |
| Test Article | | |
| Type | Longitudinal Barrier | |
| Name | TxDOT T2P Retrofit Bridge Rail | |
| Installation Length | 124 ft | |
| Material or Key Elements | Cantilevered steel-reinforced deck, curb and HSS steel rail | |
| Soil Type and Condition | | Concrete Bridge Deck, Dry |
| Test Vehicle | | |
| Type/Designation | 10000S | |
| Make and Model | 2012 Hino 338 SUT | |
| Curb | 13,950 lb | |
| Test Inertial | 22,540 lb | |
| Dummy | No dummy | |
| Gross Static | 22,540 lb | |
| Impact Conditions | | |
| Speed | 56.3 mi/h | |
| Angle | 14.2° | |
| Location/Orientation | 4.4 ft upstream of post 6 | |
| Impact Severity | | 144 kip-ft |
| Exit Conditions | | |
| Speed | Rode off end | |
| Trajectory/Heading Angle | Rode off end | |
| Occupant Risk Values | | |
| Longitudinal OIV | 5.4 ft/s | |
| Lateral OIV | 11.4 ft/s | |
| Longitudinal Ridedown | 2.1 g | |
| Lateral Ridedown | 3.9 g | |
| THIV | 3.9 m/s | |
| ASI | 0.4 | |
| Max. 0.050-s Average | | |
| Longitudinal | -1.6 g | |
| Lateral | 3.4 g | |
| Vertical | -1.7 g | |
| Post-Impact Trajectory | | |
| Stopping Distance | 241 ft downstream | |
| | 12 ft twd field side | |
| Vehicle Stability | | |
| Maximum Roll Angle | 42° | |
| Maximum Pitch Angle | 12° | |
| Maximum Yaw Angle | 25° | |
| Vehicle Snagging | Yes | |
| Vehicle Pocketing | No | |
| Test Article Deflections | | |
| Dynamic | 14.9 inches | |
| Permanent | 9.0 inches | |
| Working Width | 64.4 inches | |
| Height of Working Width | 144.3 inches | |
| Vehicle Damage | | |
| VDS | NA | |
| CDC | 11FLEW4 | |
| Max. Exterior Deformation | 10.0 inches | |
| OCDI | NA | |
| Max. Occupant Compartment Deformation | None | |

Figure 5.7. Summary of Results for MASH Test 4-12 on TxDOT T2P Retrofit Bridge Rail.

Chapter 6. SUMMARY AND CONCLUSIONS

6.1. ASSESSMENT OF TEST RESULTS

The crash test reported herein was performed in accordance with *MASH* Test 4-12 on the TxDOT T2P retrofit bridge rail. Table 6.1 provides an assessment of the test based on the applicable safety evaluation criteria for *MASH* TL-4 longitudinal barriers.

6.2. CONCLUSIONS

The TxDOT T2P retrofit bridge rail met the performance criteria for *MASH* Test 4-12 for longitudinal barriers.

Table 6.1. Performance Evaluation Summary for MASH Test 4-12 on TxDOT T2P Retrofit Bridge Rail.

Test Agency: Texas A&M Transportation Institute

Test No.: 440861-2

Test Date: 2021-07-23

| MASH Test 4-12 Evaluation Criteria | Test Results | Assessment |
|---|---|-------------------|
| <p><u>Structural Adequacy</u></p> <p>A. <i>Test article should contain and redirect the vehicle or bring the vehicle to a controlled stop; the vehicle should not penetrate, underide, or override the installation although controlled lateral deflection of the test article is acceptable.</i></p> | <p>The TxDOT T2P retrofit bridge rail contained and redirected the 1000S vehicle. The vehicle did not penetrate, underide, or override the installation. Maximum dynamic deflection during the test was 14.9 inches.</p> | <p>Pass</p> |
| <p><u>Occupant Risk</u></p> <p>D. <i>Detached elements, fragments, or other debris from the test article should not penetrate or show potential for penetrating the occupant compartment, or present an undue hazard to other traffic, pedestrians, or personnel in a work zone.</i></p> <p><i>Deformations of, or intrusions into, the occupant compartment should not exceed limits set forth in Section 5.2.2 and Appendix E of MASH.</i></p> | <p>No detached elements, fragments, or other debris from the bridge rail were present to penetrate or show potential for penetrating the occupant compartment, or to present undue hazard to others in the area.</p> <p>No deformation or intrusion of the occupant compartment occurred.</p> | <p>Pass</p> |
| <p>G. <i>It is preferable, although not essential, that the vehicle remain upright during and after collision.</i></p> | <p>The 1000S vehicle remained upright during and after the collision event. Maximum roll and pitch angles were 42 degrees and 12 degrees.</p> | <p>Pass</p> |

Chapter 7. IMPLEMENTATION*


The TxDOT T2P bridge rail as tested in this project on a 6-inch-thick deck with a single layer of reinforcing steel (#5 bars; 40 ksi or greater) at 12 inches on the centers each way, as shown herein, is recommended for implementation for *MASH* TL-4. This retrofit design is recommended on all existing bridges with deck details that meet or exceed these as-tested conditions.

* The opinions/interpretations identified/expressed in this section of the report are outside the scope of TTI Proving Ground's A2LA Accreditation.

REFERENCES

1. AASHTO. *Manual for Assessing Roadside Safety Hardware, Second Edition*. American Association of State Highway and Transportation Officials, Washington, DC, 2016.


APPENDIX A. DETAILS OF TXDOT T2P RETROFIT BRIDGE RAIL



| | |
|------------------|---|
| | Roadside Safety and Physical Security Division - Proving Ground |
| | Project #440861-2 T2P Retrofit |
| Drawn by GES | Scale 1:200 |
| Sheet 1 of 8 | Test Installation |
| Date: 2021-05-10 | Drawing: 440861-2-440861-2 |

- 1a. All Posts, Hardware and Rail components shall be galvanized.
- 1b. Typical 3 places at each Post. Plate Washer, Hex Nut, and Lock Washer typical x 2 at each U-bolt location.



Q:\Accreditation-17025-2017\EIR-000 Project Files\440861 - TXDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting, 440861-2\440861-2 Drawing



| | | |
|--------------|---|---------------------------|
| | Roadside Safety and Physical Security Division - Proving Ground | |
| | Project #440861-2 T2P Retrofit | 2021-05-10 |
| Drawn by GES | Scale 1:200 | Sheet 2 of 8 Deck Details |


Q:\Accreditation-17025-2017\IER-000 Project Files\440861 - TxDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting_440861-2\440861-2 Drawing

Curb Details



Detail G
Scale 1 : 20

Z-1, in pairs, with 9" overlap (Adjust overlap at joint and ends to maintain coverage.)




3a. All rebar dimensions are to center of bar unless otherwise indicated by "cvt" (cover).
3b. Concrete in Curb is 4,000 psi.



Roadside Safety and Physical Security Division - Proving Ground

| | |
|--------------------------------|---------------------------|
| Project #440861-2 T2P Retrofit | 2021-05-10 |
| Drawn by GES Scale 1:200 | Sheet 3 of 8 Curb Details |









- 4a.** Core Ø3/4" holes in Deck for B-1 and B-2 Rods. Percussion drilling is not permitted.
- 4b.** All rebar dimensions are to center of bar unless otherwise indicated by "cvt" (cover). All rebar in the curb is grade 60. For longitudinal reinforcement in the curb, Lap length is 27" for #5 Bars and 18" for #3 bars.
- 4c.** Hardware is typical at B-1 and B-2 Rods.

| | | |
|--------------|---|--------------------------------------|
| | Roadside Safety and Physical Security Division - Proving Ground | 2021-05-10 |
| | Project #440861-2 T2P Retrofit | Sheet 4 of 8 Curb Cross Section, etc |
| Drawn by GES | Scale 1:5 | |

Q:\Accreditation-17025-2017\IER-000 Project Files\440861 - TxDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting_440861-2\440861-2 Drawing

Bar Details


Threads not shown on threaded rods for clarity.



Roadside Safety and
Physical Security Division -
Proving Ground

| | |
|--------------------------------|-------------|
| Project #440861-2 T2P Retrofit | 2021-05-10 |
| Drawn by GES | Scale 1:10 |
| Sheet 5 of 8 | Bar Details |

Q:\Accreditation-17025-2017\ER-000 Project Files\440861 - TxDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting_440861-2\440861-2 Drawing



**Texas A&M
 Transportation
 Institute**


Roadside Safety and
 Physical Security Division -
 Proving Ground

Project #440861-2 T2P Retrofit 2021-05-10

Drawn by GES Scale 1:30 Sheet 7 of 8 Rail Details

Q:\Accreditation-17025-2017\TIER-000 Project Files\440861 - TxDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting_440861-2\440861-2 Drawing

Joint Sleeves and U-bolt



T2P U-bolt
 Ø1/2" x 10"
 ASTM A36 Steel

| | | |
|--------------|---|---------------------------------------|
| | Roadside Safety and Physical Security Division - Proving Ground | |
| | Project #440861-2 T2P Retrofit | 2021-05-10 |
| Drawn by GES | Scale 1:5 | Sheet 8 of 8 Joint Sleeves and U-bolt |

Q:\Accreditation-17025-2017\EIR-000 Project Files\440861 - TxDOT FY2021\440861-02 T2P Retrofit - Williams\Drafting_440861-2\440861-2 Drawing

APPENDIX B. SUPPORTING CERTIFICATION DOCUMENTS



Certificate of Compliance

CUSTOMER: CMC
CUSTOMER PO #: 883800
MADDEN BOLT SO#: 122801

BOLTS: A193-B7
HEX NUTS: _____
FLAT
WASHER: _____
LOCK
WASHER: _____
COATING: A153
TEMPLATE: _____
OTHER: _____

NOTES: _____

Madden Bolt certifies that the above material is in compliance with the chemical and physical requirements of the ASTM or AISI specifications.

Thank you,

Authorized Signature:  _____
James Dagen

Date: June 7, 2021

13420 Hempstead HWY ● Houston, TX 77040 ● PH (713) 939-9999 ● FAX (713) 9397200

WWW.MADDENBOLT.COM



June 7, 2021
Madden Bolt Corporation
13420 Hempstead Hwy.
Houston, TX 77040

RE: Galvanization Certificate of Compliance
To Whom It May Concern:

We certify that our Hot Dip process meets the requirements of ASTM A123 Specification on the following order.

CUSTOMER #: CMC

SALES ORDER #: 122801 **PURCHASE ORDER #:** 883800


Approved By: _____

A handwritten signature in black ink, appearing to read 'Roger Trejo', is written over a horizontal line.

Roger Trejo

13420 Hempstead HWY ● Houston, TX 77040 ● PH (713) 939-9999 ● FAX (713) 9397200

WWW.MADDENBOLT.COM

| | | | | | | | | | |
|--|---------|--|-------|---|--------|------|------|-------|---------|
|  | | Vulcan Threaded Products 10 Cross Creek Trail Pelham, AL 35124 Tel (205) 620-5100 Fax (205) 620-5150 | | <h2>JOB MATERIAL CERTIFICATION</h2> | | | | | |
| Job No: 521519 | | Job Information | | Certified Date: 4/10/17 | | | | | |
| Containers: S12601892 S12601893 S12601894 S12601895 S12601896 | | Customer: The Lawless Group | | Ship To: 2200 Alberta Suite 130 Dallas, TX 75229 | | | | | |
| Vulcan Part No: ATR B7 5/8x12 Customer Part No: ATR B7 5/8x12 Customer PO No: Stock Transfer Order No: 322035 Note: | | | | Shipped Qty: 5 containers Line No: 47 | | | | | |
| Applicable Specifications | | | | | | | | | |
| Type Heat Treat | | Specification ASTM F1554 Gd 105 S4 ASME SA-193/SA-193M B7 ASTM A193 B7 | | Rev 2015 2013 2016 | | | | | |
| | | | | Amend 2016 | | | | | |
| | | | | Option | | | | | |
| Test Results See following pages for tests | | | | | | | | | |
| Certified Chemical Analysis | | | | | | | | | |
| Heat No: 10478270 | | | | Origin: USA | | | | | |
| C | Mn | P | S | Si | Cr | Mo | NI | V | Cu |
| 0.420 | 0.89 | 0.010 | 0.025 | 0.28 | 0.92 | 0.21 | 0.05 | 0.003 | 0.08 |
| Al | Nb | Sn | Ti | N | B | DI | RR | G.S. | Macro S |
| 0.026 | 0.003 | 0.006 | 0.002 | 0.0070 | 0.0001 | 5.37 | 99.1 | Fine | 2 |
| Macro R | Macro C | J1 | J2 | J3 | J4 | J5 | J6 | J7 | J8 |
| 2 | 2 | 57 | 57 | 57 | 57 | 57 | 57 | 57 | 56 |
| J9 | J10 | J12 | J14 | J16 | J18 | J20 | J24 | J28 | J32 |
| 54 | 53 | 50 | 49 | 46 | 46 | 45 | 43 | 41 | 38 |
| Notes | | | | | | | | | |
| Material was manufactured, tested and inspected in accordance with Vulcan Threaded Products Inc. Quality Assurance Program and Manual Rev. A, dated 8/23/11. Processed material is Quenched and Tempered - Stress Free. No weld repair performed on the material. No Mercury used in the production of this material. Melted and Manufactured in the USA. Document is in accordance with EN 10204 - 3.1B of 2004 (3.1). | | | | | | | | | |

Plex 4/10/17 10:28 AM vulc.mgri Page 1 of 2

[Signature] 4/10/17

ATR
 1
 PE69664
 10478270
 Vulcan
 5/8X12ATR
 87

Page 1 of 2

https://www.plexonline.com/7d6be42e-8c10-4ec9-9df0-6c625b6ab9a7/Sales/Report_Job_Cert.asp?Mode... 7/18/2017



Vulcan Threaded Products
 10 Cross Creek Trail
 Pelham, AL 35124
 Tel (205) 620-5100
 Fax (205) 620-5150

JOB MATERIAL CERTIFICATION

Job No: 521519

Job Information

Certified Date: 4/10/17

Containers: S12601892 S12601893 S12601894 S12601895 S12601896

Test Results

Part No: BAR B7 .5626x288

Test No: 42225 Test: Quench & Temper Information (Lbs)

| Description | Tempering Temp (F) | Run Speed (Ft/min) | Quench Water Temp (F) | Austenitizing Temp (F) | Note |
|-------------------------------------|--------------------|--------------------|-----------------------|------------------------|------|
| Quench & Temper Information Results | 1,337 | 36 | 85 | 1,627 | |

Test No. 42226 Test: A193 B7, F1554-105 Requirements

| Description | Tensile (ksi) | Yield 0.2% Offset (ksi) | Elongation (%) | Elongation Gage Length | ROA (%) | Midradius Hardness | Surface Hardness | Center Hardness | Hardness Test Type | Note |
|-------------|---------------|-------------------------|----------------|------------------------|---------|--------------------|------------------|-----------------|--------------------|------|
| 138 | 129 | 24 | 4D | 62 | 30 | 29 | | | HRC | |
| 139 | 131 | 23 | 4D | 62 | 29 | 28 | | | HRC | |
| 136 | 127 | 19 | 4D | 61 | 30 | 29 | | | HRC | |
| 137 | 128 | 24 | 4D | 62 | 28 | 28 | | | HRC | |
| 139 | 130 | 24 | 4D | 65 | 30 | 28 | | | HRC | |

Test No. 42227 Test: F1554-15 gd105 S4 Charpy ft/lbs Requirements

| Description | Container | Test Temp (F) | Test1 (ft/lbs) | Test2 (ft/lbs) | Test3 (ft/lbs) | Results Avg (ft/lbs) | Note |
|-------------|-----------|---------------|----------------|----------------|----------------|----------------------|------|
| | | -20 | 157 | 147 | 125 | 143 | |

Griffin, Mitchell - Certification Engineer

4/10/17

Date

Page 2 of 2



CMC STEEL TEXAS
1 STEEL MILL DRIVE
SEGUIN TX 78155-7510

CERTIFIED MILL TEST REPORT
For additional copies call
830-372-8771

We hereby certify that the test results presented here
are accurate and conform to the reported grade specification

Rolando A. Davila

Quality Assurance Manager

| Characteristic | Value | Characteristic | Value | Characteristic | Value |
|---|------------------------------|-------------------------------------|-------|-------------------------------------|-------|
| HEAT NO.: | 3104351 | CMC Construction Svcs College Stati | S | CMC Construction Svcs College Stati | S |
| SECTION: | REBAR 16MM (#5) 20'0" 300/40 | CMC Construction Svcs College Stati | I | CMC Construction Svcs College Stati | I |
| GRADE: | ASTM A615-20 Grade 300/40 | 10650 State Hwy 30 | P | 10650 State Hwy 30 | P |
| ROLL DATE: | 03/17/2021 | College Station TX | T | College Station TX | T |
| MELT DATE: | 03/17/2021 | US 77845-7950 | O | US 77845-7950 | O |
| Cert. No.: | 83406649 / 104351A138 | 979 774 5900 | | 979 774 5900 | |
| Delivery#: | 83406649 | | | | |
| BOL#: | 74060369 | | | | |
| CUST PO#: | 879203 | | | | |
| CUST P/N: | | | | | |
| DLVRY LBS / HEAT: | 4006.000 LB | | | | |
| DLVRY PCS / HEAT: | 192 EA | | | | |
| C | 0.09% | | | | |
| Mn | 0.83% | | | | |
| P | 0.013% | | | | |
| S | 0.048% | | | | |
| Si | 0.18% | | | | |
| Cu | 0.38% | | | | |
| Cr | 0.17% | | | | |
| Ni | 0.12% | | | | |
| Mo | 0.034% | | | | |
| V | 0.000% | | | | |
| Cb | 0.001% | | | | |
| Sn | 0.013% | | | | |
| Al | 0.001% | | | | |
| Yield Strength test 1 | 57.0ksi | | | | |
| Tensile Strength test 1 | 93.7ksi | | | | |
| Elongation test 1 | 15% | | | | |
| Elongation Gage Lgth test 1 | 8IN | | | | |
| Bend Test 1 | Passed | | | | |
| Bend Test Diameter | 2.188IN | | | | |
| <p>The Following is true of the material represented by this MTR:</p> <ul style="list-style-type: none"> *Material is fully killed *100% melted and rolled in the USA *EN10204:2004 3.1 compliant *Contains no weld repair *Manufactured in accordance with the latest version of the plant quality manual *Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661 *Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov | | | | | |

REMARKS :



CMC STEEL TEXAS
1 STEEL MILL DRIVE
SEGUIN TX 78155-7510

CERTIFIED MILL TEST REPORT
For additional copies call
830-372-8771

We hereby certify that the test results presented here
are accurate and conform to the reported grade specification

Rolando A Davila

Quality Assurance Manager

| S O L D T O | | S H I P T O | | S H I P T O | |
|---|-------|---|-------|---|-------|
| CMC Construction Svcs College Stati | | CMC Construction Svcs College Stati | | CMC Construction Svcs College Stati | |
| Characteristic | Value | Characteristic | Value | Characteristic | Value |
| HEAT NO.: 3104270 SECTION: REBAR 16MM (#5) 40" 420/60 GRADE: ASTM A615-20 Gr 420/60 ROLL DATE: 03/14/2021 MELT DATE: 03/14/2021 Cert. No.: 83411185 / 104270A765 | | | | | |
| 10650 State Hwy 30 College Station TX US 77845-7950 T 979 774 5900 | | 10650 State Hwy 30 College Station TX US 77845-7950 T 979 774 5900 | | 10650 State Hwy 30 College Station TX US 77845-7950 T 979 774 5900 | |
| Yield Strength test 1 | | 68.9ksi | | The Following is true of the material represented by this MTR: *Material is fully killed *100% melted and rolled in the USA *EN10204:2004 3.1 compliant *Contains no weld repair *Contains no Mercury contamination *Manufactured in accordance with the latest version of the plant quality manual *Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661 *Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov | |
| Tensile Strength test 1 | | 107.9ksi | | | |
| Elongation test 1 | | 15% | | | |
| Elongation Gage Lgth test 1 | | 8IN | | | |
| Tensile to Yield ratio test 1 | | 1.57 | | | |
| Bend Test 1 | | Passed | | Bend Test Diameter 2.188IN | |
| REMARKS : | | | | | |



CMC STEEL TEXAS
1 STEEL MILL DRIVE
SEGUIN TX 78155-7510

CERTIFIED MILL TEST REPORT
For additional copies call
830-372-8771

We hereby certify that the test results presented here
are accurate and conform to the reported grade specification

Rolando A. Davila
Quality Assurance Manager

| Characteristic | | Value | |
|---|-------------------------------------|----------------------------|-------------------------------------|
| HEAT NO.: 3102819 | | | |
| SECTION: REBAR 13MM (#4) 40'0" 420/60 | | | |
| GRADE: ASTM A615-20 Gr 420/60 | | | |
| ROLL DATE: 01/16/2021 | | | |
| MELT DATE: 01/05/2021 | | | |
| Cert. No.: 83346589 / 102819A371 | | | |
| S | CMC Construction Svcs College Stati | S | CMC Construction Svcs College Stati |
| O | 10650 State Hwy 30 | H | 10650 State Hwy 30 |
| L | College Station TX | I | College Station TX |
| D | US 77845-7950 | P | US 77845-7950 |
| T | 979 774 5900 | T | 979 774 5900 |
| O | | O | |
| Characteristic | | Characteristic | |
| C | 0.44% | Bend Test Diameter 1.750IN | |
| Mn | 0.79% | | |
| P | 0.032% | | |
| S | 0.047% | | |
| Si | 0.17% | | |
| Cu | 0.34% | | |
| Cr | 0.09% | | |
| Ni | 0.11% | | |
| Mo | 0.040% | | |
| V | 0.000% | | |
| Cb | 0.001% | | |
| Sn | 0.011% | | |
| Al | 0.001% | | |
| Yield Strength test 1 | | | |
| Tensile Strength test 1 | | | |
| Elongation test 1 | | | |
| Elongation Gage Lgth test 1 | | | |
| Tensile to Yield ratio test1 | | | |
| Bend Test 1 | | | |
| 63.0ksi | | | |
| 101.3ksi | | | |
| 13% | | | |
| 8IN | | | |
| 1.61 | | | |
| Passed | | | |
| <p>The Following is true of the material represented by this MTR:</p> <ul style="list-style-type: none"> *Material is fully killed *100% melted and rolled in the USA *EN10204:2004 3.1 compliant *Contains no weld repair *Contains no Mercury contamination *Manufactured in accordance with the latest version of the plant quality manual *Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661 *Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov | | | |

REMARKS :

We hereby certify that the test results presented here

are true and correct to the best of our knowledge and belief.

RECEIVED MILL TEST REPORT
 Additional copies call
 820-372-3777

CMC TEST REPORT
 1 STEEL MILL
 SECURID EX 78155 7510



[Signature]
 Rolando A Davila
 Quality Assurance Manager

| | | | | | |
|---------------------------------------|---|------------------------------------|---|------------------------------------|---------------------------|
| HEAT NO: A3104459 | S | CMC Construction Svcs College Blvd | S | CMC Construction Svcs College Blvd | D-Inventory: 37409953 |
| SECTION: REBAR 10MM (#3) 20'0" 450/50 | O | 1000 S. State Hwy 30 | H | 1000 S. State Hwy 30 | ROLL#: 74065495 |
| GRADE: ASTM A615-20 G. 42-50 | D | College Station TX | | College Station TX | ENCL: 12/27/2020 |
| ROLL DATE: 03/21/2021 | | 778457950 | | US 77935 7950 | PLANT MFG: |
| MELT DATE: 03/21/2021 | | | | 579 79 | PLANT LDS/HEAT: 100000000 |
| Part, Mat, Comp: 1010-450059 | O | | | | |

| Characteristic | Value | Characteristic | Value |
|------------------------------|----------|--------------------|---------|
| C | 0.45% | Bend Test Diameter | 1.313IN |
| Mn | 0.68% | | |
| P | 0.012% | | |
| S | 0.040% | | |
| Si | 0.16% | | |
| Cu | 0.27% | | |
| Cr | 0.11% | | |
| Ni | 0.12% | | |
| Mo | 0.041% | | |
| V | 0.000% | | |
| Cb | 0.001% | | |
| Sn | 0.009% | | |
| Al | 0.001% | | |
| Yield Strength test 1 | 72.7ksi | | |
| Tensile Strength test 1 | 112.8ksi | | |
| Elongation test 1 | 13% | | |
| Elongation Gage Lgth test 1 | 8IN | | |
| Tensile to Yield ratio test1 | 1.55 | | |
| Bend Test 1 | Passed | | |

The Following is true of the material represented by this MTR:
 *Material is fully killed
 *100% melted and rolled in the USA
 *EN10204.2004 3.1 compliant
 *Contains no weld repair
 *Manufactured in accordance with the latest version of the plant quality manual
 *Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661
 *Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

REMARKS :

We hereby certify that the test results presented here

are true and correct to the best of our knowledge and belief.

Signature of Quality Assurance Manager

Signature of Test Operator

Signature of Inspector



CMC
1 ST
8155 7510

Roberto A. Duran
Quality Assurance Manager

Delivery #: 3310073
BOI #: 74065652

CMC Construction Svcs Collage Strat
77845 7050

CMC Construction Svcs Collage Strat
77845 7050

CMC Construction Svcs Collage Strat
77845 7050

Value

C 0.45%

Mn 0.71%

P 0.010%

S 0.048%

Si 0.16%

Cu 0.28%

Cr 0.08%

Ni 0.11%

Mo 0.044%

V 0.000%

Cb 0.001%

Sn 0.010%

Al 0.002%

Yield Strength test 1 69.0ksi

Tensile Strength test 1 107.3ksi

Elongation test 1 13%

Elongation Gage Lgth test 1 8IN

Tensile to Yield ratio test 1 1.56

Bend Test 1 Passed

Bend Test Diameter 1.3131i

Character

The Following is true of the material represented by this MTR:

*Material is fully killed

*100% melted and rolled in the USA

*EN10204:2004 3.1 compliant

*Contains no weld repair

*Contains no Mercury contamination

*Manufactured in accordance with the latest version of the plant quality manual

*Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661

*Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

REMARKS :



CMC STEEL TEXAS
1 STEEL MILL DRIVE
SEGUIN TX 78155-7510

CERTIFIED MILL TEST REPORT
For additional copies call
830-372-8771

We hereby certify that the test results presented here
are accurate and conform to the reported grade specification

Rolando A. Davila
Quality Assurance Manager

| HEAT NO.: 3104709 | | S O L D T O | | S H I P T O | | Delivery#: 83418931 BOL#: 74080324 CUST PO#: 880219 CUST P/N: DLVRY LBS / HEAT: 41629.000 LB DLVRY PCS / HEAT: 3116 EA | |
|---|----------|-------------------------------------|---------|-------------------------------------|--|---|--|
| SECTION: REBAR 13MM (#4) 20" 420/60 | | CMC Construction Svcs College Stati | | CMC Construction Svcs College Stati | | | |
| GRADE: ASTM A615-20 Gr 420/60 | | 10650 State Hwy 30 | | 10650 State Hwy 30 | | | |
| ROLL DATE: 04/04/2021 | | College Station TX | | College Station TX | | | |
| MELT DATE: 03/31/2021 | | US 77845-7950 | | US 77845-7950 | | | |
| Cert. No.: 83418931 / 104709A130 | | 979 774 5900 | | 979 774 5900 | | | |
| Characteristic Value | | Characteristic Value | | Characteristic Value | | Characteristic Value | |
| C | 0.45% | Bend Test Diameter | 1.750IN | | | | |
| Min | 0.77% | | | | | | |
| P | 0.031% | | | | | | |
| S | 0.049% | | | | | | |
| Si | 0.17% | | | | | | |
| Cu | 0.32% | | | | | | |
| Cr | 0.13% | | | | | | |
| Ni | 0.14% | | | | | | |
| Mo | 0.052% | | | | | | |
| V | 0.000% | | | | | | |
| Cb | 0.000% | | | | | | |
| Sn | 0.015% | | | | | | |
| Al | 0.001% | | | | | | |
| Yield Strength test 1 | 66.1ksi | | | | | | |
| Tensile Strength test 1 | 105.3ksi | | | | | | |
| Elongation test 1 | 15% | | | | | | |
| Elongation Gage Lgth test 1 | 8IN | | | | | | |
| Tensile to Yield ratio test1 | 1.59 | | | | | | |
| Bend Test 1 | Passed | | | | | | |
| REMARKS : | | | | | | | |
| The Following is true of the material represented by this MTR: *Material is fully killed *100% melted and rolled in the USA *EN10204:2004 3.1 compliant *Contains no weld repair *Contains no Mercury contamination *Manufactured in accordance with the latest version of the plant quality manual *Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661 *Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov | | | | | | | |



CMC STEEL TEXAS
1 STEEL MILL DRIVE
SEGUIN TX 78155-7510

CERTIFIED MILL TEST REPORT
For additional copies call
830-372-8771

We hereby certify that the test results presented here
are accurate and conform to the reported grade specification

Rolando A Davila
Quality Assurance Manager

| HEAT NO.: 3104707 | S O L D T O | CMC Construction Svcs College Stati | S H I P T O | CMC Construction Svcs College Stati | Delivery#: 83418931 BOL#: 74080324 CUST PO#: 880219 CUST P/N: DLVRY LBS / HEAT: 6573.000 LB DLVRY PCS / HEAT: 492 EA |
|---|----------------------------|---|---|-------------------------------------|---|
| SECTION: REBAR 13MM (#4) 20'0" 420/60 | | 10650 State Hwy 30 College Station TX US 77845-7950 979 774 5900 | 10650 State Hwy 30 College Station TX US 77845-7950 979 774 5900 | | |
| GRADE: ASTM A615-20 Gr 420/60 | | | | | |
| ROLL DATE: 04/04/2021 | | | | | |
| MELT DATE: 03/31/2021 | | | | | |
| Cert. No.: 83418931 / 104707A130 | | | | | |
| Characteristic Value | Characteristic Value | | Characteristic Value | | Characteristic Value |
| C 0.44% | Bend Test Diameter 1.750IN | | | | |
| Min 0.69% | | | | | |
| P 0.028% | | | | | |
| S 0.042% | | | | | |
| Si 0.16% | | | | | |
| Cu 0.30% | | | | | |
| Cr 0.12% | | | | | |
| Ni 0.17% | | | | | |
| Mo 0.065% | | | | | |
| V 0.000% | | | | | |
| Cb 0.001% | | | | | |
| Sn 0.013% | | | | | |
| Al 0.001% | | | | | |
| Yield Strength test 1 66.6ksi | | | | | |
| Tensile Strength test 1 106.2ksi | | | | | |
| Elongation test 1 16% | | | | | |
| Elongation Gage Lgth test 1 8IN | | | | | |
| Tensile to Yield ratio test1 1.59 | | | | | |
| Bend Test 1 Passed | | | | | |
| <p>The Following is true of the material represented by this MTR:</p> <ul style="list-style-type: none"> *Material is fully killed *100% melted and rolled in the USA *EN10204:2004 3.1 compliant *Contains no weld repair *Contains no Mercury contamination *Manufactured in accordance with the latest version of the plant quality manual *Meets the "Buy America" requirements of 23 CFR635.410, 49 CFR 661 *Warning: This product can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov | | | | | |
| REMARKS : | | | | | |

| TTI Rail Retrofit - TTI - J. | | | | |
|-------------------------------------|-------------|--------------------|-------------|------------|
| QTY | SIZE | DESCRIPTION | BEND | TAG |
| | | GRADE 60 | | |
| 125 | 4 | 5'-6" | | |
| 34 | 4 | 11' x 10" x 11" | ZBAR | Z1 |
| | | | | |
| 85 | 5 | 7" x 2'-0" | LBAR | L2 |
| 248 | 5 | 7½" x 11" x 7½" | UBAR | U1 |
| | | | | |
| 15 | 5 | 20' | | |
| 51 | 4 | 20' | | |
| 15 | 3 | 20' | | |
| | | | | |
| | | GRADE 40 | | |
| 126 | 5 | 2'-8" x 3'-10" | LBAR | L1 |
| 67 | 5 | 20' | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

v

TUCKER _ c o n c r e t e

970-777-6749

TUCKER_CONSTRUCTION
TTI

TICKET # 863

START DATE: 2021-04-16 TIME: 10:34:57
STOP DATE: 2021-04-16 TIME: 11:21:00

MIX DESIGN: B1400
RAW CEMENT COUNTS: 465
RAW CONVEYOR COUNTS: 253806

TOTAL YARDS 10.89

| MATERIAL | RATE SETTING | TOTAL |
|----------|--------------|----------|
| CEMENT | 7.74225LBS/ | 5634.582 |
| SAND | 4.853882LBS | 14843.67 |
| STONE | 5.997994LBS | 20499.96 |
| WATER | 24.49684GAL | 279.9608 |
| ADMIX #1 | 0.00Z/MIN | 0.00Z |
| ADMIX #2 | 116.80765OZ | 1430.014 |
| ADMIX #3 | 0.00Z/MIN | 0.00Z |
| DRY COLO | 0.0LBS/MIN | 0.0LBS |

TOTAL SAND MOISTURE: 5.0
TOTAL STONE MOISTURE: 1.0
WATER/CEMENT RATIO: 0.582753
ASTM DATA AVAILABLE UPON REQ

Name _____

NOTES: _____

TUCKER_c o n c r e t e

979-777-6749

TRUCK #4

TUCKER_CONSTRUCTION

TTI

TICKET # 634

START DATE: 2021-04-16 TIME: 10:59:33

STOP DATE: 2021-04-16 TIME: 11:49:32

MIX DESIGN: B1400

RAW CEMENT COUNTS: 6147

RAW CONVEYOR COUNTS: 209022

CONVEYOR SPEED: 50

TOTAL YARDS 9.747

| MATERIAL | RATE SETTING | TOTAL |
|---------------------------|--------------|----------|
| CEMENT | 9.343309LBS | 5039.31L |
| SAND | 5.397386 GA | 13277.23 |
| ADJUSTED: | | |
| STONE | 7.101724 GA | 18336.62 |
| ADJUSTED: | | |
| WATER | 30.01423GAL | 269.6036 |
| ADMIX #1 | 0.00Z/MIN | 0.00Z |
| ADMIX #2 | 0.00Z/MIN | 0.00Z |
| ADMIX #3 | 0.00Z/MIN | 0.00Z |
| TOTAL SAND MOISTURE: 0.0 | | |
| TOTAL STONE MOISTURE: 0.0 | | |

Name

NOTES:

CONCRETE COMPRESSIVE STRENGTH TEST REPORT**Terracon**

Report Number: A1171057.0182
 Service Date: 04/16/21
 Report Date: 07/23/21 Revision 1 - Compressive Strength Test Date
 Task: PO# 440861-02

6198 Imperial Loop
 College Station, TX 77845-5765
 979-846-3767 Reg No: F-3272

Client

Texas Transportation Institute
 Attn: Gary Gerke
 TTI Business Office
 3135 TAMU
 College Station, TX 77843-3135

Project

Riverside Campus
 Riverside Campus
 Bryan, TX

Project Number: A1171057

Material Information

Specified Strength: 4,000 psi @ 28 days

Mix ID: B1400
 Supplier: Tucker Concrete
 Batch Time: 1034 Plant: Bryan
 Truck No.: 1705 Ticket No.: 863

Field Test Data

| Test | Result | Specification |
|-------------------------|--------|---------------|
| Slump (in): | 8 | Not specified |
| Air Content (%): | 1.9 | Not specified |
| Concrete Temp. (F): | 76 | 40 - 95 |
| Ambient Temp. (F): | 66 | 40 - 95 |
| Plastic Unit Wt. (pcf): | 144.7 | Not specified |
| Yield (Cu. Yds.): | | |

Sample Information

Sample Date: 04/16/21 Sample Time: 1117
 Sampled By: David Carpio
 Weather Conditions: Cloudy, light wind
 Accumulative Yards: 10.89 Batch Size (cy): 10.89
 Placement Method: Direct Discharge
 Water Added Before (gal): 0
 Water Added After (gal): 0
 Sample Location: 18' north of south end
 Placement Location: T2P

Laboratory Test Data

| Set No. | Specimen ID | Avg Diam. (in) | Area (sq in) | Date Received | Date Tested | Age at Test (days) | Maximum Load (lbs) | Compressive Strength (psi) | Fracture Type | Tested By |
|---------|-------------|----------------|--------------|---------------|-------------|--------------------|--------------------|----------------------------|---------------|-----------|
| 1 | A | 6.00 | 28.27 | | 07/22/21 | 97 F | 133,510 | 4,720 | 1 | SLS |
| 1 | B | 6.00 | 28.27 | | 07/22/21 | 97 F | 132,630 | 4,690 | 4 | SLS |
| 1 | C | 6.00 | 28.27 | | 07/22/21 | 97 F | 133,860 | 4,730 | 1 | SLS |
| 1 | D | | | | | Hold | | | | |

Initial Cure: Outside Plastic Lids

Final Cure: Field Cured

Comments: F = Field Cured

Note: Reported air content does not include Aggregate Correction Factor (ACF).

Samples Made By: Terracon

Services: Obtain samples of fresh concrete at the placement locations (ASTM C 172), perform required field tests and cast, cure, and test compressive strength samples (ASTM C 31, C 39, C 1231).

Terracon Rep.: David Carpio

Start/Stop: 1015-1245

Reported To: Will

Contractor:

Report Distribution:

(1) Texas Transportation Institute, Gary Gerke (1) Terracon Consultants, Inc., Alex Dumigan, P.E.
 (1) Texas Transportation Institute, Bill Griffith

Test Methods: ASTM C 31, ASTM C143, ASTM C231, ASTM C1064

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

CONCRETE COMPRESSIVE STRENGTH TEST REPORT

Report Number: A1171057.0182
Service Date: 04/16/21
Report Date: 07/23/21 Revision 1 - Compressive Strength Test Date
Task: PO# 440861-02

Terracon

6198 Imperial Loop
College Station, TX 77845-5765
979-846-3767 Reg No: F-3272

Client

Texas Transportation Institute
Attn: Gary Gerke
TTI Business Office
3135 TAMU
College Station, TX 77843-3135

Project

Riverside Campus
Riverside Campus
Bryan, TX

Project Number: A1171057

Material Information

Specified Strength: 4,000 psi @ 28 days

Mix ID: B1400
Supplier: Tucker Concrete
Batch Time: 1059 Plant: Bryan
Truck No.: 4 Ticket No.: 634

Sample Information

Sample Date: 04/16/21 Sample Time: 1144
Sampled By: David Carpio
Weather Conditions: Cloudy, light wind
Accumulative Yards: 9.74 Batch Size (cy): 9.74
Placement Method: Direct Discharge
Water Added Before (gal): 0
Water Added After (gal): 0
Sample Location: 57' North of south end
Placement Location: T2P

Field Test Data

| Test | Result | Specification |
|-------------------------|--------|---------------|
| Slump (in): | 5 3/4 | Not specified |
| Air Content (%): | 2.4 | Not specified |
| Concrete Temp. (F): | 75 | 40 - 95 |
| Ambient Temp. (F): | 66 | 40 - 95 |
| Plastic Unit Wt. (pcf): | 145.5 | Not specified |
| Yield (Cu. Yds.): | | |

Laboratory Test Data

| Set No. | Specimen ID | Avg Diam. (in) | Area (sq in) | Date Received | Date Tested | Age at Test (days) | Maximum Load (lbs) | Compressive Strength (psi) | Fracture Type | Tested By |
|---------|-------------|----------------|--------------|---------------|-------------|--------------------|--------------------|----------------------------|---------------|-----------|
| 2 | A | 6.00 | 28.27 | | 07/22/21 | 97 F | 137,910 | 4,880 | 1 | SLS |
| 2 | B | 6.00 | 28.27 | | 07/22/21 | 97 F | 156,450 | 5,530 | 4 | SLS |
| 2 | C | 6.00 | 28.27 | | 07/22/21 | 97 F | 139,360 | 4,930 | 4 | SLS |
| 2 | D | | | | | Hold | | | | |

Initial Cure: Outside Plastic Lids

Final Cure: Field Cured

Comments: F = Field Cured

Note: Reported air content does not include Aggregate Correction Factor (ACF).

Samples Made By: Terracon

Services: Obtain samples of fresh concrete at the placement locations (ASTM C 172), perform required field tests and cast, cure, and test compressive strength samples (ASTM C 31, C 39, C 1231).

Terracon Rep.: David Carpio

Start/Stop: 1015-1245


Reported To: Will

Contractor:

Report Distribution:

(1) Texas Transportation Institute, Gary Gerke (1) Terracon Consultants, Inc., Alex Dunigan, P.E.
(1) Texas Transportation Institute, Bill Griffith

Reviewed By:



Alexander Dunigan
Project Manager

Test Methods: ASTM C 31, ASTM C143, ASTM C231, ASTM C1064

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

TUCKER Concrete

8930 LACY WELL RD
77845 979 777 6749

Job # TUCKER
TTI T2P

TICKET # 1094
START DATE: 06/14/2021 TIME: 07:46:26
STOP DATE: 06/14/2021 TIME: 08:33:52

MIX DESIGN B1500
RAW CEMENT COUNTS 6930
RAW CONVEYOR COUNTS 2584

TOTAL YARDS 4.24

| MATERIAL | RATE SETTING | TOTAL |
|----------|--------------|-----------|
| CAPTYPE1 | 448.3LBPM | 2592.5LBS |
| LRMSAND | 4.6 GATE | 5611.5LBS |
| RGBLND | 5.7 GATE | 7749.9LBS |
| WATER | 23.5GPM | 133.4GAL |
| SIKA686 | 0.9GPM | 5.1GAL |

WATER / CEMENT RATIO 0.43
REQUEST ASTM INFORMATION

NAME _____
NOTES:

CONTINUED FROM 1093

CONCRETE COMPRESSIVE STRENGTH TEST REPORT

Report Number: A1171057.0200
Service Date: 06/14/21
Report Date: 07/23/21 Revision 2 - 38-day results
Task: PO# 440861-02

Terracon

6198 Imperial Loop
College Station, TX 77845-5765
979-846-3767 Reg No: F-3272

Client

Texas Transportation Institute
Attn: Gary Gerke
TTI Business Office
3135 TAMU
College Station, TX 77843-3135

Project

Riverside Campus
Riverside Campus
Bryan, TX

Project Number: A1171057

Material Information

Specified Strength: 4,000 psi @ 28 days
Mix ID: B1500
Supplier: Tucker concrete
Batch Time: 0746 Plant: Onsite
Truck No.: VM1801 Ticket No.: From onsite

Sample Information

Sample Date: 06/14/21 Sample Time: 0800
Sampled By: Ethan Boultinghouse
Weather Conditions: Clear, no wind
Accumulative Yards: 2.0 Batch Size (cy): 4.24
Placement Method: Direct Discharge
Water Added Before (gal): 0
Water Added After (gal): 0
Sample Location: 8th section of edge wall on north side of airfield
Placement Location: Curb T2P

Field Test Data

| Test | Result | Specification |
|-------------------------|--------|---------------|
| Slump (in): | 5 | |
| Air Content (%): | 2.4 | |
| Concrete Temp. (F): | 82 | |
| Ambient Temp. (F): | 85 | |
| Plastic Unit Wt. (pcf): | 145.1 | |
| Yield (Cu. Yds.): | | |

Laboratory Test Data

| Set No. | Specimen ID | Avg Diam. (in) | Area (sq in) | Date Received | Date Tested | Age at Test (days) | Maximum Load (lbs) | Compressive Strength (psi) | Fracture Type | Tested By |
|---------|-------------|----------------|--------------|---------------|-------------|--------------------|--------------------|----------------------------|---------------|-----------|
| 1 | A | 6.01 | 28.37 | | 06/18/21 | 4 | 95,630 | 3,370 | 1 | SLS |
| 1 | B | 6.00 | 28.27 | | 07/22/21 | 38 | 125,440 | 4,440 | 3 | SLS |
| 1 | C | 6.00 | 28.27 | | 07/22/21 | 38 | 128,520 | 4,550 | 3 | SLS |
| 1 | D | 6.00 | 28.27 | | 07/22/21 | 38 | 126,320 | 4,470 | 1 | SLS |
| | | | | | | | Average (38 days) | 4,480 | | |

Initial Cure: Outside Plastic Lids

Final Cure: Field Cured

Comments: Average compressive strength of 38 day cylinders complies with the specified strength.

Note: Reported air content does not include Aggregate Correction Factor (ACF).

Samples Made By: Terracon

Services: Obtain samples of fresh concrete at the placement locations (ASTM C 172), perform required field tests and cast, cure, and test compressive strength samples (ASTM C 31, C 39, C 1231).

Terracon Rep.: Ethan Boultinghouse

Start/Stop: 0645-0900


Reported To:

Contractor:

Report Distribution:

(1) Texas Transportation Institute, Gary Gerke (1) Terracon Consultants, Inc., Alex Dunigan, P.E.
(1) Texas Transportation Institute, Bill Griffith

Reviewed By:



Alexander Dunigan
Project Manager

Test Methods: ASTM C 31, ASTM C143, ASTM C231, ASTM C1064


The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials.

APPENDIX C. MASH TEST 4-12 (CRASH TEST NO. 440861-2)

C.1. VEHICLE PROPERTIES AND INFORMATION

Table C.1. Vehicle Properties for Test No. 440861-2.

Date: 2021-07-23 Test No.: 440861-2 VIN No.: 5PVNV8JM5C4S50273
 Year: 2012 Make: HINO Model: 338
 Odometer: 212617 Tire Size Front: 275/80R22.5 Tire Size Rear: 275/80R22.5



| | | | | | | | | |
|---|----------------------------------|--|----|------------------------------|-------------------|----|-----------------------------|---------------|
| Vehicle Geometry: | | <input checked="" type="checkbox"/> inches | or | <input type="checkbox"/> mm | | | | |
| A | Front Bumper Width: | <u>92.50</u> | K | Rear Bumper Bottom: | <u> </u> | U | Cab Length: | <u>107.00</u> |
| B | Overall Height: | <u>135.00</u> | L | Rear Frame Top: | <u>39.00</u> | V | Trailer/Box Length: | <u>224.00</u> |
| C | Overall Length: | <u>332.25</u> | M | Front Track Width: | <u>79.00</u> | W | Gap Width: | <u>1.50</u> |
| D | Rear Overhang: | <u>86.50</u> | N | Roof Width: | <u>77.50</u> | X | Overall Front Height: | <u>104.75</u> |
| E | Wheel Base: | <u>205.75</u> | O | Hood Height: | <u>60.00</u> | Y | Roof-Hood Distance: | <u>34.50</u> |
| F | Front Overhang: | <u>40.00</u> | P | Bumper Extension: | <u>1.00</u> | Z | Roof-Box Height Difference: | <u>30.25</u> |
| G | C.G. Height: | <u> </u> | Q | Front Tire Width: | <u>39.50</u> | AA | Rear Track Width: | <u>73.00</u> |
| H | C.G. Horizontal Dist. w/Ballast: | <u>131.62</u> | R | Front Wheel Width: | <u>23.25</u> | BB | Ballast Center of Mass: | <u>63.75</u> |
| I | Front Bumper Bottom: | <u>18.75</u> | S | Bottom Door Height: | <u>38.25</u> | CC | Cargo Bed Height: | <u>50.75</u> |
| J | Front Bumper Top: | <u>31.50</u> | T | Overall Width: | <u>97.00</u> | | | |
| Allowable Range: C = 394 inches max.; E = 240 inches max.; CC = 49 ±2 inches; BB = 63 ±2 inches above ground; | | | | | | | | |
| | Wheel Center Height Front | <u>19.00</u> | | Wheel Well Clearance (Front) | <u>13.25</u> | | Bottom Frame Height (Front) | <u>24.75</u> |
| | Wheel Center Height Rear | <u>19.00</u> | | Wheel Well Clearance (Rear) | <u>4.00</u> | | Bottom Frame Height (Rear) | <u>28.75</u> |

More information needed on next page →

Table C.1. Vehicle Properties for Test No. 440861-2 (Continued).

Date: 2021-07-23 Test No.: 440861-2 VIN No.: 5PVNV8JM5C4S50273
 Year: 2012 Make: HINO Model: 338

WEIGHTS
 lb or kg)

| | CURB | TEST INERTIAL |
|-------------------------|--------------|---------------|
| W _{front axle} | <u>6850</u> | <u>8120</u> |
| W _{rear axle} | <u>7100</u> | <u>14420</u> |
| W _{TOTAL} | <u>13950</u> | <u>22540</u> |

Allowable Range for CURB = 13,200 ±2200 lb | Allowable Range for TIM = 22,046 ±660 lb

Ballast: 8590 lb or kg (as-needed)
 (See MASH Section 4.2.1.2 for recommended ballasting)

Mass Distribution

lb or kg): LF: 4060 RF: 4060 LR: 7410 RR: 7010

Engine Type: T 260
 Engine Size: _____

Accelerometer Locations (inches or mm)
 x¹ y z²

Transmission Type:
 Auto or Manual
 FWD RWD 4WD

| | Front: | | |
|---------|---------------|-------------|--------------|
| Center: | <u>131.50</u> | <u>0.00</u> | <u>50.00</u> |
| Rear: | <u>233.00</u> | <u>0.00</u> | <u>50.00</u> |

Describe any damage to the vehicle prior to test: None


Other notes to include ballast type, dimensions, mass, location, center of mass, and method of attachment:

Two concrete blocks 30 inches high x 60 inches wide x 30 inches long
Centered in middle of bed
63.75 inches from ground to center of block
Tied down with four 5/8-inch B7 rod and four 3/8-inch cables

Performed by: SCD Date: 2021-07-23

¹ Referenced to the front axle
² Above ground

C.2. SEQUENTIAL PHOTOGRAPHS



0.000 s



0.100 s



0.200 s



0.300 s



Figure C.1. Sequential Photographs for Test No. 440861-2 (Overhead and Frontal Views).




0.400 s



0.500 s



0.600 s



0.700 s



Figure C.1. Sequential Photographs for Test No. 440861-2 (Overhead and Frontal Views) (Continued).



0.000 s



0.400 s



0.100 s



0.500 s



0.200 s



0.600 s



0.300 s



0.700 s

Figure C.2. Sequential Photographs for Test No. 440861-2 (Rear View).

C.3. VEHICLE ANGULAR DISPLACEMENTS




Figure C.3. Vehicle Angular Displacements for Test No. 440861-2.

C.4. VEHICLE ACCELERATIONS





Figure C.4. Vehicle Longitudinal Accelerometer Trace for Test No. 440861-2 (Accelerometer Located at Center of Gravity).

Y Acceleration at CG



Test Number: 440861-2
 Test Standard Test Number: MASH Test 4-12
 Test Article: TxDOT T2P Retrofit Bridge Rail
 Test Vehicle: 2012 Hino 338 SUT
 Inertial Mass: 22,540 lb
 Gross Mass: 22,540 lb
 Impact Speed: 56.3 mi/h
 Impact Angle: 14.2 degrees

Figure C.5. Vehicle Lateral Accelerometer Trace for Test No. 440861-2 (Accelerometer Located at Center of Gravity).

Z Acceleration at CG





Figure C.6. Vehicle Vertical Accelerometer Trace for Test No. 440861-2
(Accelerometer Located at Center of Gravity).

X Acceleration at Rear of Vehicle



— SAE Class 60 Filter — 50-msec average

Test Number: 440861-2
 Test Standard Test Number: MASH Test 4-12
 Test Article: TxDOT T2P Retrofit Bridge Rail
 Test Vehicle: 2012 Hino 338 SUT
 Inertial Mass: 22,540 lb
 Gross Mass: 22,540 lb
 Impact Speed: 56.3 mi/h
 Impact Angle: 14.2 degrees

Figure C.7. Vehicle Longitudinal Accelerometer Trace for Test No. 440861-2
 (Accelerometer Located at Rear of Vehicle).

Y Acceleration at Rear of Vehicle




Figure C.8. Vehicle Lateral Accelerometer Trace for Test No. 440861-2
 (Accelerometer Located at Rear of Vehicle).

Z Acceleration at Rear of Vehicle




Figure C.9. Vehicle Vertical Accelerometer Trace for Test No. 440861-2 (Accelerometer Located at Rear of Vehicle).