



# Project Summary

Texas Department of Transportation

## 0-6120: An Evaluation of the Performance of High Impact Signs

### *Background*

There are approximately 15,000 exit gore signs installed on Texas highways. Because of their frequency and exposure to high-speed traffic, they are one of the most commonly struck signs by errant vehicles, and they present a significant maintenance challenge for TxDOT. There is concern regarding the safety of personnel working in gore areas to replace these signs, and the resources necessary for continual maintenance. The objective of this research was to identify and evaluate alternative signing methods that may reduce the number of sign hits as well as the costs and resources required for sign replacement and maintenance.

### *What the Researchers Did*

Researchers visited several sites with problems related to frequent sign hits. They collected data and recorded drive-through videos to determine the factors that most likely contributed to the frequent sign hits. They compiled a list of common problems and recommended countermeasures that could potentially address some of the issues identified. Researchers also evaluated the impact of the absence of exit gore signs at two freeway exits in Corpus Christi, where advance warning with overhead exit signs were provided, and there were no visibility and sight distance issues. Since exit gore signs are required by the *Manual on Uniform Traffic Control Devices* (MUTCD) their removal for the purpose of field evaluations was not possible. Therefore, a different approach was used by taking advantage of events when exit gore signs were knocked down by vehicles. The time window between sign hit and reinstallation provided researchers the opportunity to collect data in the absence of exit gore signs.

### *What They Found*

Table 1 summarizes the most common factors contributing to vehicle crashes with exit gore signs. Table 2 summarizes a list of countermeasures that could potentially address some of the issues identified.

The field evaluations at two freeway exits in Corpus Christi showed that the absence of exit gore signs did not have any negative consequence in terms of vehicle speeds, drivers' deceleration behaviors, and erratic maneuvers.

### *Research Performed by:*

Texas Transportation Institute (TTI),  
The Texas A&M University System

### **Research Supervisor:**

Geza Pesti, TTI

### **Researchers:**

Kwaku Obeng-Boampong, TTI

Praprut Songchitruksa, TTI

LuAnn Theiss, TTI

**Project Completed:** 8-31-10

**Table 1. Factors Contributing to Frequent Exit Gore Sign Hits.**

Category	Factors
Roadway design	<ul style="list-style-type: none"> <li>Limited sight distance due to vertical and/or horizontal curve upstream of exit ramp</li> <li>Significant weaving between closely spaced ramps</li> <li>Shift in horizontal alignment of main lanes</li> <li>Constrained right-of-way</li> <li>Significantly lower advisory speed for ramp and/or frontage road</li> <li>Drop-lane design coupled with limited sight distance</li> </ul>
Driver behavior	<ul style="list-style-type: none"> <li>Inattentive driving (e.g., cell phone use, texting)</li> <li>Late decision-making</li> <li>Excessive speed</li> </ul>
Sign location and/or placement	<ul style="list-style-type: none"> <li>Visual clutter with other signs</li> <li>Exit gore sign located too close to pavement</li> </ul>
Pavement markings	<ul style="list-style-type: none"> <li>Faded/worn-out</li> <li>Lane delineators broken or uprooted</li> </ul>
Nighttime visibility	<ul style="list-style-type: none"> <li>Poor nighttime visibility on inadequately lighted roadways</li> </ul>

**Table 2. Potential Countermeasures.**

Issues	Countermeasures
High operating speeds on approach to exit	Pavement markings as passive speed control devices (Converging chevrons, transverse bars, peripheral lines)
Relatively large speed difference between main line and exit ramp speed	Rumble strips on approach lane to exit
	Ramp speed painted on the pavement in the approach lane to the exit
	Advance ramp advisory speed warning sign with flashers
Vehicle crashes with exit gore sign	Relocation of exit gore sign farther into gore area
Late exiting or merging maneuvers	Flexible pylons to delineate gore area
Vehicles crossing gore area	“Escape” lane (on freeway and/or exit ramp)
Poor nighttime visibility	Retroreflective sheeting on sign posts
	Reflective object markers on sign posts
Poor delineation & visibility of gore area	Impact attenuator with large retroreflective bi-directional arrows

## What This Means

The field study results suggest that there are locations where overhead exit signs provide sufficient advance warning and exit gore signs may not be needed. Changes to the MUTCD providing more flexibility in determining the need for these signs could result in many being eliminated at several freeway exits, which could reduce the number of sign hits as well as the costs and resources required for sign replacement and maintenance.

*For More Information:*

Research Engineer - Wade Odell, TxDOT, 512-416-4730  
 Project Director - Ismael Soto, TxDOT, 361-808-2225  
 Research Supervisor - Geza Pesti, TTI, 979-845-9878

*Technical reports when published are available at:*  
<http://library.ctr.utexas.edu/index.html>

[www.txdot.gov](http://www.txdot.gov)  
 keyword: research



Research and Technology  
 Implementation Office  
 P.O. Box 5080  
 Austin, Texas 78763-5080  
 512-416-4730

This research was performed in cooperation with the Texas Department of Transportation and the Federal Highway Administration. The contents of this report reflect the views of the authors, who are responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the official view or policies of the FHWA or TxDOT. This report does not constitute a standard, specification, or regulation, nor is it intended for construction, bidding, or permit purposes. Trade names were used solely for information and not for product endorsement.